

# Product Change Notice



**PCN:** DC1000M\_PCN\_01  
**Date:** 5/29/2020

17600 Newhope Street  
Fountain Valley, CA 92708  
USA

---

**Type of Change:** Firmware change

---

**Reason for Change:** Firmware bug fixes and maintenance updates

---

**Description of Change(s):**

1. Fixed Hot Plug issue on some version of SuperMicro Servers
2. Fixed UEFI HII detect drive issue
3. Fixed IOL TEST 2.2 Case3 timeout issue
4. Disable retention task

Firmware revision change:  
Current firmware version – S68F0115  
New firmware versions – S68F0120

**Note:** Firmware S68F0120 is a running production change and is a mandatory field update for DC1000M SSD running firmware level S68F0115.

---

**Product(s) Affected:**

SEDC1000M-960G  
SEDC1000M/1920G  
SEDC1000M/3840G  
SEDC1000M/7680G

SEDC1000M/960GBK  
SEDC1000M/1920GBK  
SEDC1000M/3840GBK  
SEDC1000M/7680GBK

---

**Contact Information:** Contact your Kingston Sales Representative for more information.

---

**Transition/Replacement Product:** Running change. No change to part/model number(s).

**Samples Available:** Now

---

**Target Phase-in Date:** 5/29/2020

Note: Lack of acknowledgement of this PCN within 30 days constitutes acceptance of change; Implementation date is subject to change.