



DCP1000 Firmware Release Notes

Firmware Revision E7FTD4.7 – September 18, 2017

SEDC1000H/800G
SEDC1000H/1600G
SEDC1000H/3200G



KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

Firmware Rev. E7FTD4.7 (9/18/17)

- Active State Power Management (ASPM) support in firmware is disabled to improve platform compatibility
- Tuning of Force Unit Access (FUA) behavior resulting in minor performance improvement

Previous Firmware Revisions

N/A (No Release Date)	<ul style="list-style-type: none">• Original firmware release
--------------------------	---