



## **SXS2000 / DTMAX Firmware Release Notes**

---

Firmware Revision S9800111 – December 25, 2022

- *SXS2000/500G*
- *SXS2000/1000G*
- *SXS2000/2000G*
- *DTMAX/256GB*
- *DTMAX/512GB*
- *DTMAX/1TB*
- *DTMAXA/256GB*
- *DTMAXA/512GB*
- *DTMAXA/1TB*



KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.



### **Firmware Rev. S9800111 (12-25-2022)**

- Fixed an issue where drives sometimes reported an incorrect USB speed

### **Previous Firmware Revisions:**

#### **Firmware Rev. S9800110 (02-25-2022)**

- Improved system compatibility
- Improved compatibility with suspend and resume
- Fixed a write speed performance drop present in some systems running Windows 11
- Improved temperature display in SMART