Release Notes for SKC100S3, Firmware Rev. 503 (08/22/12)

- Restored a minor TRIM performance variation from a previous Firmware release

- Fixed a power management condition where the device failed to respond to a COMWAKE, which might have resulted in the SSD becoming unresponsive thereby requiring a reset by the host.

Release Notes for SKC100S3, Firmware Rev. 502 (06/05/12)

- Improved handling of a COMRESET command during AH CCMDT testing

- Improved responsiveness when resuming from sleep states

- Fixed incidental case that resulted in a flash command time out

- Fixed the handling of internal read buffers when reporting UECC error

Release Notes for SKC100S3, Firmware Rev. 501 (03/06/12)

- Enhanced reliability during power cycles and secure erases

- Resolved a unique issue that would block a TRIM command sent by an application while in IDE mode using Windows XP or Windows 7

- Enhanced TRIM throughput

- Improved write performance