



SHPM2280P2 Firmware Release Notes

Firmware Revision OC34L5TP – 11/16/15

- *SHPM2280P2H/240G*
- *SHPM2280P2H/480G*
- *SHPM2280P2/240G*
- *SHPM2280P2/480G*

KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

Firmware Rev. **OC34L5TP** (11/16/15)

- Enables RAID compatibility with Z170 chipset
- Resolves issue where BIOS will hang on Z170 chipset when RAID is enabled

Previous Firmware Revisions

OC34L5TM (10/05/15)	<ul style="list-style-type: none">• Resolves issue where implementing the Windows® 10 upgrade via OS update causes the system to hang and prevent completion of update
-------------------------------	--