



Release Notes for SVP200S3, SVP200S37A - Firmware Rev. 507KC4 (09/25/13)

- Resolved a unique incorrect value bug affecting SMART attribute 231
- Improved platform compatibility when using Secure Erase command
- Enhanced overall system compatibility.

Release Notes for SVP200S3, SVP200S37A - Firmware Rev. 505ABBF0 (No Release Date)

- Improved latency during error handling

Release Notes for SVP200S3, SVP200S37A - Firmware Rev. 504ABBF0 (No Release Date)

- Corrected normalized value calculation for SMART attribute 9 (Power-on Hours)

Release Notes for SVP200S3, SVP200S37A - Firmware Rev. 503ABBF0 (08/22/12)

- Restored a minor TRIM performance variation from a previous Firmware release
- Fixed a power management condition where the device failed to respond to a COMWAKE, which might have resulted in the SSD becoming unresponsive thereby requiring a reset by the host