

Product Change Notice



PCN: PCN_SEDC1500M_C1

Date: 11/30/21

17600 Newhope Street
Fountain Valley, CA 92708
USA

Type of Change: Firmware change

Reason for Change: Bug Fixes

Description of Change(s):

Firmware Rev. S67F0104 (03-11-2022)

1. Fixes related to error correction code (ECC) and PCIe error handling
2. Fixed device no detect after performing firmware update action 1 and a warm reboot
3. Modify bit setting related to deleting and recreating namespaces

Firmware revision change:

Current firmware version – S67F0103

New firmware versions – S67F0104

Note: This firmware is not available as a field upgrade. New production only.

Product(s) Affected:

SEDC1500M/960G	SEDC1500M/960GBK
SEDC1500M/1920G	SEDC1500M/1920GBK
SEDC1500M/3840G	SEDC1500M/3840GBK
SEDC1500M/7680G	SEDC1500M/7680GBK

Manufacturing Target Phase-in Date: Q3 2022

Contact Information: Contact your Kingston Sales Representative for more information.

Transition/Replacement Product: Running change. No change to part/model number(s).
