

Product Change Notice



PCN: PCN_SEDC500_C1
Date: 9/3/2019

17600 Newhope Street
Fountain Valley, CA 92708
USA

Type of Change: Component and firmware change

Reason for Change: DRAM component availability, minor maintenance updates

Description of Change(s):

1. The current Micron DDR4 DRAM component used on DC500R and DC500M has limited availability. In order to maintain consistent product availability, Kingston has qualified a second source DDR4 DRAM component (PSC DDR4) for use on certain DC500R/M BOMs. This component change has no effect in any way on the specifications, fit, form and function of the DC500R/M SSDs.
2. DRAM handling improvement

Firmware revision change:
Current firmware version – SCEKJ2.3
New firmware versions – SCEKJ2.7 and SCEKJ2.8

Note: This update is a running change and does not necessitate a field firmware update to existing DC500R/M SSDs.

Product(s) Affected:

SEDC500R/480G	SEDC500M/480G
SEDC500R-960G	SEDC500M/960G
SEDC500R/1920G	SEDC500M/1920G
SEDC500R/3840G	SEDC500M/3840G
SEDC500R/480GBK	SEDC500M/480GBK
SEDC500R/960GBK	SEDC500M/960GBK
SEDC500R/1920GBK	SEDC500M/1920GBK
SEDC500R/3840GBK	SEDC500M/3840GBK

Contact Information: Contact your Kingston Sales Representative for more information.

Transition/Replacement Product: Running change. No change to part/model number(s).

Samples Available: 9/3/2019

Target Phase-in Date: 10/15/2019

Note: Lack of acknowledgement of this PCN within 30 days constitutes acceptance of change; Implementation date is subject to change.