

Product Change Notice



PCN: PCN_SEDC500_C2

Date: 11/30/21

**17600 Newhope Street
Fountain Valley, CA 92708
USA**

Type of Change: Firmware change

Reason for Change: Bug Fix

Description of Change(s):

1. Fixed a rare corner-case issue that could cause the drive to become unresponsive until it is power-cycled

Firmware revision change:

Current firmware version – SCEKJ2.7

New firmware versions – SCEKJ2.8

Note: This update is a running change and does not necessitate a field firmware update to existing DC500R or DC500M SSDs. This update is recommended if the change description above resembles a problem you are encountering.

Product(s) Affected:

SEDC500R/480G	SEDC500M/480G
SEDC500R/960G	SEDC500M/960G
SEDC500R/1920G	SEDC500M/1920G
SEDC500R/480GBK	SEDC500M/480GBK
SEDC500R/960GBK	SEDC500M/960GBK
SEDC500R/1920GBK	SEDC500M/1920GBK

Firmware Available: 11/30/2021

Manufacturing Target Phase-in Date: 12/17/2021

Contact Information: Contact your Kingston Sales Representative for more information.

Transition/Replacement Product: Running change. No change to part/model number(s).
