



## **SKC400S37 & SHSS37A Firmware Release Notes**

---

Firmware Revision SAFM001B – December 15th, 2016

*SKC400S37/128G*  
*SKC400S37/256G*  
*SKC400S37/512G*  
*SKC400S37/1T*

*SHSS37A/120G*  
*SHSS37A/240G*  
*SHSS37A/480G*  
*SHSS37A/960G*

KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

### **Firmware Rev. SAFM001B (12/15/16)**

- Resolved corner case behavior that forces drive into ROM mode after an abnormal initialization causing it to register as 2MB
- Modified Identify Word 47/59 for 3<sup>rd</sup>-party software compatibility
- Reduced aggregation of TRIM resulting in improved performance and responsiveness

### **Previous Firmware Revisions**

<b>N/A</b> (No Release Date)	<ul style="list-style-type: none"><li>• Original firmware releases</li></ul>
---------------------------------	--