



SHFS37A Firmware Release Notes

Firmware Revision 60AABBF0 – May 28th, 2016

- *SHFS37A/120G*
- *SHFS37A/240G*
- *SHFS37A/480G*



KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

Firmware Rev. 60AABBF0 (05/28/16)

- Fixed case where drive will temporarily become unreadable causing IO errors which may lead to OS freezing. Power cycle of the SSD will resolve the issue.
- Improved accuracy of SMART (177) wear leveling attribute

Previous Firmware Revisions

580ABBF0 (07/02/14)	<ul style="list-style-type: none">• Improved drive stability• Enhanced overall system compatibility
541ABBF0 (No Release Date)	<ul style="list-style-type: none">• Original firmware at launch