



SKC3000 / SFYR Firmware Release Notes

Firmware Revision EIFK31.7 – July 08, 2024

- *SKC3000S/512G*
- *SKC3000S/1024G*
- *SKC3000D/2048G*
- *SKC3000D/4096G*
- *SFYRS/500G*
- *SFYRS/1000G*
- *SFYRD/2000G*
- *SFYRD/4000G*
- *SFYRSK/500G*
- *SFYRSK/1000G*
- *SFYRDK/2000G*
- *SFYRDK/4000G*



KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

Firmware Rev. EIFK31.7 (07-08-2024)

- Improved decoding flow to prevent excessive latency found on certain platforms