

PCN: PCN_SEDC500R_C3 **Date:** 6/16/23

17600 Newhope Street Fountain Valley, CA 92708 USA

KINGS

Type of Change: DRAM & firmware change

Reason for Change: DRAM component availability and firmware update

Description of Change(s):

To maintain consistent product continuity, a pre-qualified second source of DRAM was utilized within the DC500R 480G/960G/1920G BOMs starting in Sep'22. Initially, those BOMs shipped with SCEKJ2.7 firmware and did not require a firmware upgrade to SCEKJ2.8 that previous BOMs required. However, to ensure a more uniform firmware revision throughout the product line, effective Jun'23, firmware revision SCEKJ2.8 has been qualified and will be phased in for the models noted below. The new DRAM and firmware changes do not affect any of the specifications, form, fit and function of the DC500R SSDs.

Product(s) Affected:

SEDC500R/480G SEDC500R/960G SEDC500R/1920G

SEDC500R/480GBK SEDC500R/960GBK SEDC500R/1920GBK

Transition/Replacement Product:

Running change effective Jun'23 for new builds, no change to part/model number(s).

Contact Information:

Contact your Kingston Sales Representative for more information at https://www.kingston.com/en/company/contacts

Kingston Technology Company, Inc. 17600 Newhope Street Fountain Valley, CA 92708 USA www.kingston.com