

Product Change Notice



PCN: PCN_SEDC600M_C1

Date: 11/28/2023

17600 Newhope Street
Fountain Valley, CA 92708
USA

Type of Change: DRAM Component change

Reason for Change: DRAM component availability

Description of Change(s):

The current Micron DDR4 DRAM component used with SEDC600M/3840G and SEDC600M/7680G has limited availability. These SKUs will transition to using SK Hynix DDR4 DRAM for all future builds. This component change has no effect in any way to the specifications, fit, form or function of the SSD. This update is a running change, and no firmware change is necessary.

Product(s) Affected:

SEDC600M/3840G
SEDC600M/3840GBK

SEDC600M/7680G
SEDC600M/7680GBK

Contact Information:

Contact your Kingston Sales Representative for more information at <https://www.kingston.com/en/company/contacts>

Transition/Replacement Product:

Running change. No change to part/model number(s), but there will be a BOM # change. No FW change is required.

Target Phase-in Date: Jan'24