



SA2000M8 Firmware Release Notes

Firmware Revision S5Z42109 – March 30, 2021

- *SA2000M8/250G*
- *SA2000M8/500G*
- *SA2000M8/1000G*

KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

Firmware Rev. S5Z42109 (03-30-2021)

- Fixed an issue that might cause the drive to become unresponsive on Linux systems
- Fixed a compatibility issue with the Asus Armoury Crate tool

Previous Firmware Revisions:

Firmware Rev. S5Z42105 (01-10-2020)

- Improved performance in some QD1 workloads
- Improvements related to TCG Opal