



SKC600 Firmware Release Notes

Firmware Revision S4500109 – September 02, 2022

- *SKC600/256G*
- *SKC600/512G*
- *SKC600/1024G*
- *SKC600/2048G*
- *SKC600MS/256G*
- *SKC600MS/512G*
- *SKC600MS/1024G*



KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

Firmware Rev. S4500109 (09-02-2022)

- Fixed an issue related to the SMART error log
- Fixed an issue related to trim

Previous Firmware Revisions:**Firmware Rev. S4500107 (10-27-2020)**

- Improved RAID compatibility

Firmware Rev. S4500105 (01-10-2020)

- Added SMART attribute E7h
- Improvements related to TCG Opal